



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

**FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL**

PMA Design and Manufacturing  
8493 Baymeadows Way  
Jacksonville, FL 32256  
(904) 292-2329

PMA No.: PQ1570CE  
Supplement No.: 156  
Date: December 6, 2019

Article Name	Article Number	Approved Replacement for Article Number	Approval Basis and Approved Design Data	Make/TCH Eligibility	Model/Series Eligibility
Harness and Lap Belt Assy	PDM0108006-XX (See Note)	0108006-03	Test and Computations per 14 CFR 21.303 DWG No: PDM-RESTRAINT Rev: - Date: 09/13/2019 or later FAA-approved revisions	Viking Air Limited	DHC-6-100, DHC-6-200, DHC-6-300, DHC-6-400
Harness and Reel Assy	PDM2B25A-XX (See Note)	2B25A1X-21 2B25A2X-21 2B25A3X-21	Test and Computations per 14 CFR 21.303 DWG No: PDM-RESTRAINT Rev: - Date: 09/13/2019 or later FAA-approved revisions	Viking Air Limited	DHC-6-100, DHC-6-200, DHC-6-300, DHC-6-400
Lap Belt Assy	PDM1101020-XX (See Note)	1101020-4 1101020-9 1101020-14	Test & Computation per 14 CFR 21.303 DWG No: PDM-RESTRAINT Rev: - Date: 09/13/2019 or later FAA-approved revisions	Viking Air Limited	DHC-6-100, DHC-6-200, DHC-6-300, DHC-6-400


Note: The -XX in the article numbers above represents a variable color code identified on the applicable drawing. Additional color codes may be added via minor changes to the basic design of the PMA without new application.

-----END OF DATA-----

GENERAL NOTES:

Provide minor design changes in a manner as determined by the ACO. Process major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.

The FAA accepted the ICA approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR 21.50.

  
for Christina M. Underwood  
Manager, Atlanta ACO Branch

  
John Kolin  
Manager, Orlando MIDO Section  
System Oversight Division